

Table of Contents

ES	EXECUTIVE SUMMARY, GUALALA RIVER WATERSHED ASSESSMENT.....	ES-1
	North Coast Watershed Assessment Program	ES-1
	Salmonids, Habitat, and Land Use Relationships	ES-2
	The Gualala River Watershed.....	ES-3
	General Assessment Methods.....	ES-7
	Assessment Products.....	ES-10
	General Assessment Questions, Conclusions, and Recommendations	ES-11
	Subbasin Findings, Conclusions, and Recommendations	ES-15
1.	PROGRAM INTRODUCTION AND OVERVIEW	1-1
1.1	Salmon / Stream / Watershed / Land Use Relationships	1-2
1.1.1	Factors Affecting Anadromous Salmonid Production.....	1-4
1.1.2	Disturbance and Recovery of Stream and Watershed Conditions	1-6
1.2	Policies, Acts, and Listings	1-9
2.	ASSESSMENT STRATEGY AND GENERAL METHODS	2-1
2.1	Methods by Department	2-1
2.1.1	Hydrologic Analyses	2-1
2.1.2	Geologic Analysis.....	2-3
2.1.3	Vegetation and Land Use	2-10
2.1.4	Water Quality	2-11
2.1.5	Fish Habitat and Populations	2-14
2.2	Interdisciplinary Synthesis	2-15
2.2.1	Ecological Management Decision Support.....	2-15
2.2.2	Integrated Analyses Tables.....	2-15
2.2.3	Limiting Factors Analysis	2-16
2.2.4	Restoration Needs.....	2-17
2.2.5	Potential Salmonid Refugia	2-18
2.2.6	Development and Evaluation of Hypotheses.....	2-22
2.3	Watershed Assessment Approach in the Gualala	2-22
2.4	Assessment Report Conventions and Use	2-23
2.4.1	Report Utility and Usage	2-23
2.4.2	NCWAP Products.....	2-23
2.4.3	Calwater 2.2a Planning Watersheds	2-24
2.4.4	Hydrology Hierarchy	2-24
2.4.5	Electronic Data Conventions	2-26

3.	GUALALA WATERSHED PROFILE	3-1
3.1	Hydrology	3-3
3.2	Geology	3-6
3.2.1	Fluvial Geomorphology.....	3-7
3.3	Vegetation	3-10
3.4	Land Use	3-11
3.5	Water Quality	3-18
3.5.1	Macroinvertebrates.....	3-21
3.6	Fish/Habitat Relationships	3-22
3.6.1	Historic Fish Habitat Relationship	3-22
3.6.2	Target Values from Habitat Inventory Surveys.....	3-27
3.6.3	Current Fish habitat Relationship.....	3-28
3.6.4	Changes in Habitat Conditions from 1964 to 2001	3-28
3.7	Fish History and Status	3-33
3.7.1	Salmonid Population	3-34
3.7.2	Stocking of Coho Salmon and Steelhead Trout.....	3-39
3.7.3	Salmonid Range or Distribution	3-39
3.7.4	Fish Restrictions, Acts, Protections	3-41
3.7.5	Special-Status Species	3-44
3.7.6	Other Fish and Aquatic Organisms	3-44
4.	INTERDISCIPLINARY SYNTHESIS AND FINDINGS.....	4-1
4.1	Ecological Management Decision Support	4-2
4.1.1	Introduction	4-2
4.1.2	EMDS Development and Use by NCWAP	4-2
4.1.3	The Knowledge Base Networks	4-3
4.1.4	Advantages, Applications, and Limitations of EMDS	4-16
4.2	Integrated Analysis of Physical Features and Habitat.....	4-17
4.2.1	Landslides and Land Use/Land Type	4-18
4.2.2	Relative Landslide Potential and Land Use/Land Type	4-20
4.2.3	Roads and the Landscape	4-23
4.2.4	Relative Landslide Potential and Silviculture and Yarding Methods	4-28
4.2.6	Management Implications – Land Use and Roads	4-35
4.3	Limiting Factors Analysis	4-37
4.4	Potential Restoration Opportunities	4-39
4.4.1	Map of Potential Restoration Sites and Habitat Limiting Factors	4-39
4.4.2	Priorities For Restoration in the Gualala River Tributaries	4-41
4.4.3	Gualala River Watershed General Hydrologic Characteristics	4-47
4.5	Potential Salmonid Refugia	4-50

5. SUBBASIN PROFILES AND SYNTHESIS

5.1	Gualala River Estuary	5.1-1
5.1.1	Introduction	5.1-1
5.1.2	Geology	5.1-1
5.1.3	Riparian Vegetation	5.1-3
5.1.4	Land Use.....	5.1-4
5.1.5	Fish Habitat Relationship	5.1-5
5.1.6	Subbasin Issue Synthesis and Recommendations	5.1-6
5.2	North Fork Subbasin	5.2-1
5.2.1	Introduction	5.2-1
5.2.2	Geology	5.2-1
5.2.3	Vegetation.....	5.2-1
5.2.4	Land Use.....	5.2-1
5.2.5	Roads	5.2-11
5.2.6	Fluvial Geomorphology.....	5.2-13
5.2.7	Water Quality	5.2-13
5.2.8	Fish Habitat Relationship	5.2-19
5.2.9	Fish History and Status.....	5.2-29
5.2.10	North Fork Subbasin Public Issues, Synthesis, and Recommendations	5.2-33
5.3	Rockpile Subbasin	5.3-1
5.3.1	Introduction	5.3-1
5.3.2	Geology	5.3-1
5.3.3	Vegetation.....	5.3-1
5.3.4	Land Use.....	5.3-1
5.3.5	Roads	5.3-9
5.3.6	Fluvial Geomorphology.....	5.3-11
5.3.7	Water Quality	5.3-12
5.3.8	Fish Habitat Relationships	5.3-16
5.3.9	Fish History and Status.....	5.3-24
5.3.10	Rockpile Subbasin Public Issues, Synthesis, and Recommendations	5.3-24
5.4	Buckeye Subbasin.....	5.4-1
5.4.1	Introduction	5.4-1
5.4.2	Geology	5.4-1
5.4.3	Vegetation.....	5.4-1
5.4.4	Land Use.....	5.4-1
5.4.5	Roads	5.4-10
5.4.6	Fluvial Geomorphology.....	5.4-14
5.4.7	Water Quality	5.4-14
5.4.8	Fish Habitat Relationships	5.4-18
5.4.9	Fish History and Status.....	5.4-24
5.4.10	Buckeye Subbasin Public Issues, Synthesis, and Recommendations	5.4-27

5.5	Wheatfield Subbasin	5.5-1
5.5.1	Introduction	5.5-1
5.5.2	Geology	5.5-1
5.5.3	Vegetation	5.5-1
5.5.4	Land Use.....	5.5-6
5.5.5	Roads	5.5-11
5.5.6	Fluvial Geomorphology.....	5.5-15
5.5.7	Water Quality	5.5-16
5.5.8	Fish Habitat Relationship	5.5-21
5.5.9	Fish History and Status.....	5.5-30
5.5.10	Wheatfield Fork Subbasin Public Issues, Synthesis, and Recommendations .	5.4-34
5.6	Gualala Mainstem/South Fork Subbasin.....	5.6-1
5.6.1	Introduction	5.6-1
5.6.2	Geology	5.6-1
5.6.3	Vegetation	5.6-1
5.6.4	Land Use.....	5.6-8
5.6.5	Roads	5.6-12
5.6.6	Fluvial Geomorphology.....	5.6-13
5.6.7	Water Quality	5.6-14
5.6.8	Fish Habitat Relationship	5.6-18
5.6.9	Fish History and Status.....	5.6-26
5.4.10	Gualala Mainstem/South Fork Subbasin Public Issues, Synthesis, and Recommendations	5.6-29
6.	LIMITATIONS OF THE ASSESSMENT	6-1
7.	REFERENCES CITED	7-1
8.	GLOSSARY	8-1
9.	LIST OF ABBREVIATIONS.....	9-1
10.	APPENDICES (Separate Document)	
	1. Hydrology	
	2. Geology	
	3. Land Use	
	4. Water Quality	
	5. Fisheries	
	6. Synthesis	
	7. Public Responsiveness Summary	

LIST OF FIGURES

ES-1	Gualala River Watershed Streams and Towns.....	ES-4
ES-2	The Gualala River Watershed with NCWAP subbasins and Calwater 2.2a Planning Watersheds.....	ES-9
3-1	NCWAP Subbasins in the Gualala River Watershed, California.....	3-2
3-2	Distribution of Channel Gradients in the Gualala River Watershed.....	3-8
3-3	Distribution of the Excess Sediment in the Gualala River Watershed in 2000, Mainly in Low-Gradient Reaches.....	3-9
3-4	Distribution of Landslides in the Gualala River Watershed.....	3-10
3-5	1961 Aerial photo, Post World War II Pre-Forest Practice Rules Logging in the Buckeye Subbasin.....	3-12
3-6	Cumulative Stand Replacement Operations 1942 – 1973, and Post 1973 Operations and THPs.....	3-14
3-7	1942 Bank-to-Bank Stream Exposure in Generally Undisturbed Old Growth Watershed Conditions.....	3-15
3-8	1968 Bank-to-Bank Stream Exposure.....	3-16
3-9	1999/2000 Bank-to-Bank Stream Exposure, Reflecting Vegetational Ingrowth Since 1968.....	3-17
3-10	North Fork Gualala Macroinvertebrate Data, 2001.....	3-22
3-11	Stocking Records from 1969-99 for Coho Salmon and Steelhead Trout in the Gualala River Watershed, California.....	3-35
3-12	Historic coho salmon (<i>Oncorhynchus kisutch</i>) distribution based on CDFG stream reports from pre-planting in 1964 and post-planting 1970 in the Gualala River Watershed, California. The coho salmon young-of-the-year observed on Robinson Creek (1998) and Dry Creek (1998 and 2002) were not included on this map.....	3-42
3-13	Current observed steelhead trout (<i>Oncorhynchus mykiss</i>) distribution based on observations (1970-present), and CDFG habitat inventories and electrofishing surveys in 1995, 1999, and 2001 in the Gualala River Watershed, California.....	3-43
4.1-1	NCWAP EMDS Anadromous Reach Condition Model.....	4-4
4.1-2	NCWAP EMDS Potential Sediment Production Model.....	4-5
4.1-3	NCWAP EMDS Fish Food Availability, Water Quality and Fish Habitat Quality Models.....	4-6
4.1-4	EMDS Stream Reach Knowledge Base Network.....	4-7
4.1-5	EMDS Reference Curve.....	4-8
4.1-6	Using the 10 th and 90 th percentiles as breakpoints (as with land use) is a linear approximation of the central part of the normalized cumulative distribution function.....	4-9
4.1-7	EMDS Graphical Output, Density of Roads Proximate to Streams.....	4-11

4.2-1 Mid-20th-Century tractor logging areas shown in three separate time strata, and in-stream/streamside roads and landings 4-24

4.2-2 Segments of Modern Roads Located within 50 Feet of Blue Line Streams (Red), with 1991 to 2001 Timber Harvest Plans indicated 4-27

4.2-3 Fluvial Geomorphic Channel Disturbances Detrimental to Optimum Habitats for Anadromous Salmonids Mapped from Aerial Photographs for the Gualala River Watershed 4-34

4.4-1 Areas Habitat Inventoried in the Gualala River Watershed (Figure 3 of Appendix 5) 4-42

5.1-1 Aerial Photos of the Gualala River Estuary in 1936 and 1961 5.1-5

5.1-2 Aerial Photos of the Gualala River Estuary in 1981 and 1999 5.1-5

5.2-1 North Fork Gualala River Subbasin 5.2-2

5.2-2 Historic Events and Data Used in the NCWAP Assessment for the North Fork Gualala River Subbasin 5.2-3

5.2-3 Geologic and Geomorphic Features Related to Landsliding - North Fork Subbasin 5.2-4

5.2-4 Relative Landslide Potential with Geologic and Geomorphic Features – North Fork Subbasin 5.2-5

5.2-5 Lower to Middle Reaches of the North Fork Subbasin, 1936, Showing Mid-Sized Second Growth Redwood Stands 5.2-6

5.2-6 Confluence with Dry Creek, 1936..... 5.2-6

5.2-7 1936 Bank-to-Bank Stream Exposure..... 5.2-7

5.2-8 Old Growth Tractor Logging by 1963 in the Central Reaches of the North Fork Subbasin, at the Confluence with Stewart Creek 5.2-8

5.2-9 Mid-Century Tractor Operations and Streamside/In-stream Roads and Landings..... 5.2-8

5.2-10 Smaller Debris Slides and Debris Flows 5.2-9

5.2-11 Bank-to-Bank Shade Canopy Exposure from 1968 and 2000 5.2-9

5.2-12 Timber Harvest Plans from 1991 to 2001..... 5.2-11

5.2-13 In-stream Sediment Sampling Sites, North Fork Subbasin..... 5.2-15

5.2-14 In-stream Temperature Sampling Sites, North Fork Subbasin..... 5.2-16

5.2-15 Maximum Weekly Average Temperature (MWAT) Ranges for the North Fork Subbasin from 1994-2001..... 5.2-17

5.2-16 MWAT Temperature Ranges in the North Fork Subbasin for the Period of Record, 1994-2001 Overlaid on the Landsat Vegetation Layer for 2000..... 5.2-18

5.2-17 Canopy Cover and Canopy Vegetation Types in the North Fork Subbasin 2001, Gualala River Watershed, California 5.2-21

5.2-18 Canopy Cover and Canopy Vegetation Types in the North Fork Subbasin, measured by the Gualala River Watershed Council, Gualala River Watershed, California 5.2-21

5.2-19	Cobble Embeddedness in the North Fork Subbasin 2001, Gualala River Watershed, California	5.2-22
5.2-20	Pools by Maximum Depth and Percent Survey Length in the North Fork Subbasin 2001, Gualala River Watershed, California	5.2-23
5.2-21	Average Pool Shelter Ratings in the North Fork Subbasin 2001, Gualala River Watershed, California.....	5.2-23
5.2-22	Type of Pool Shelter/Cover by Percent of Pool Survey Length in the North Fork Subbasin 2001, Gualala River Watershed, California.....	5.2-24
5.2-23a	Potential Restoration Sites and Habitat Limiting Factors for the North Fork Subbasin, Gualala River Watershed.....	5.2-31
5.2-23b	Explanation for Potential Restoration Sites and Habitat Limiting Factors for the Gualala River Watershed Map.....	5.2-32
5.3-1	The Rockpile Subbasin.....	5.3-2
5.3-2	Historic Events and Data Used in the NCWAP Assessment for the Rockpile Subbasin	5.3-3
5.3-3	Geologic and Geomorphic Features Related to Landsliding - Rockpile Subbasin	5.3-4
5.3-4	Relative Landslide Potential with Geologic and Geomorphic Features – Rockpile Subbasin	5.3-5
5.3-5	Bank-to-Bank Exposure on Rockpile Creek in 1942	5.3-6
5.3-6	Central Rockpile PWS 1960 and the Same Area in 1963 Showing a Rapid Rate of Old Growth Harvesting in a Three-Year Period.....	5.3-7
5.3-7	Mid-Century Tractor Harvest Operations, and Streamside Roads and Landings	5.3-7
5.3-8	1968 Bank-to-Bank Exposure and 2000 in Rockpile Subbasin	5.3-8
5.3-9	1991 to 2001 Timber Harvest Plans	5.3-9
5.3-10	Instream Sediment and Temperature Sampling Sites, Rockpile Subbasin	5.3-13
5.3-11	Maximum Weekly Average Temperature (MWAT) Ranges For The Rockpile Subbasin From 1995-2001 (<i>Data From GRI And GRWC Continuous Monitoring Devices</i>).....	5.3-14
5.3-12	MWAT Temperature Ranges in the Rockpile Subbasin for the Period of Record, 1995-2001 Overlaid on the Lansat Vegetation Layer for 2000	5.3-15
5.3-13	Canopy Cover and Canopy Vegetation Types by Percent Survey Length in Rockpile Creek, Rockpile Subbasin 2001, Gualala River Watershed, California	5.3-17
5.3-14	Cobble Embeddedness in the Rockpile Subbasin 2001, Gualala River Watershed, California	5.3-17
5.3-15	Pools by Maximum Depth and Percent Survey Length in the Rockpile Subbasin 2001, Gualala River Watershed, California	5.3-18
5.3-16	Average Pool Shelter Ratings in the Rockpile Subbasin 2001, Gualala River Watershed, California.....	5.3-18

5.3-17 Pool Cover by Percent of Pool Survey Length in the Rockpile Subbasin 2001, Gualala River Watershed, California5.3-19

5.3-18a Potential Restoration Sites and Habitat Limiting Factors for the Rockpile Subbasin, Gualala River Watershed.....5.3-22

5.3-18b Explanation for Potential Restoration Sites and Habitat Limiting Factors for the Gualala River Watershed Map.....5.3-23

5.4-1 Buckeye Subbasin 5.4-2

5.4-2 Historic Events and Data Used in the NCWAP Assessment for the Buckeye Subbasin..... 5.4-3

5.4-3 Geologic and Geomorphic Features Related to Landsliding - Buckeye Subbasin..... 5.4-4

5.4-4 Relative Landslide Potential with Geologic and Geomorphic Features - Buckeye Subbasin 5.4-5

5.4-5 Bank-to-Bank Stream Exposure (White) and Partial to Entire Cover (Dark Blue) in 1942..... 5.4-6

5.4-6 Mid-Century Tractor Operations in the Buckeye Subbasin and Streamside Roads and Landings 5.4-6

5.4-7 Tractor yarding was active in the Grasshopper Creek basin in the mid 60s, leaving logs and wood debris piled over the stream channel. During the 1964 flood, this debris floated down to a low road crossing of Grasshopper Creek (left), creating a jam. The resulting dam breached at the south road approach, diverting onto the west road approach, which collapsed into the Creek 5.4-7

5.4-8 Middle reaches of Buckeye Creek 1960, and same area (right) by 1963 showing a high rate of old growth harvesting in a three-year time period. Franchini Creek is in the center right of each photo. Note entire bank-to-bank stream exposure as a result of these operations..... 5.4-7

5.4-9 Bank-to-Bank Canopy Exposure in the Buckeye Subbasin in 1968 and 1999 5.4-9

5.4-10 1991 to 2001 Timber Harvests..... 5.4-10

5.4-11 Instream Sediment and Temperature Sampling Sites, Buckeye Subbasin..... 5.4-15

5.4-12 Maximum Weekly Average Temperature (MWAT) Ranges For The Buckeye Subbasin From 1995-2001..... 5.4-16

5.4-13 MWAT Temperature Ranges in the Buckeye Subbasin for the Period of Record, 1995-2001 Overlaid on the Lansat Vegetation Layer for 2000 5.4-17

5.4-14 Canopy Cover and Canopy Vegetation Types by Percent Survey Length in the Buckeye Creek, Buckeye Subbasin 2001, Gualala River Watershed, California..... 5.4-20

5.4-15 Percent of Cobble Embeddedness in all Pool Tails in the Buckeye Creek Subbasin 2001, Gualala River Watershed, California 5.4-20

5.4-16 Pools by Maximum Depth and Percent Survey Length in the Buckeye Creek Subbasin 2001, Gualala River Watershed, California..... 5.4-20

5.4-17 Average Pool Shelter Ratings in the Buckeye Creek Subbasin 2001, Gualala River, California 5.4-21

5.4-18	Pool Cover Types by Percent of Pool Survey Length in the Buckeye Creek Subbasin 2001, Gualala River Watershed, California	5.4-21
5.4-19a	Potential Restoration Sites and Habitat Limiting Factors for the Buckeye Subbasin, Gualala River Watershed.....	5.4-25
5.3-19b	Explanation for Potential Restoration Sites and Habitat Limiting Factors for the Gualala River Watershed Map.....	5.4-26
5.5-1	Wheatfield Fork Subbasin	5.5-2
5.5-2	Historic Events and Data Used in the NCWAP Assessment for the North Fork Gualala River Subbasin.....	5.5-3
5.5-3	Geologic and Geomorphic Features Related to Landsliding - Wheatfield Fork Subbasin ...	5.5-4
5.5-4	Relative Landslide Potential with Geologic and Geomorphic Features - Wheatfield Fork Subbasin	5.5-5
5.5-5	1942 Bank-to-Bank Exposure, Dark Blue Shows Partial to Entire Canopy Cover Over Streams	5.5-6
5.5-6	Mid-Century Timber Harvest Operations and Streamside Roads and Landings (Red)	5.5-7
5.5-7	Conifer Block Removal Exposing Tobacco Creek and Streamside Roads Along the North Fork Fuller Creek 1965 Caltrans 1: 1200 Scale	5.5-7
5.5-8	Debris Slides Slice Through Several Road Contours, Discharging onto a Tributary Watercourse to Wheatfield Fork, at Annapolis Fire Station, 1965	5.5-8
5.5-9	Sullivan Creek Meanders Around Multiple Debris Slides Over Buried Stream Pools, June 1965.....	5.5-8
5.5-10	1968 Bank-to-Bank Stream Shade Canopy Exposure. 1999 Bank-to-Bank Shade Canopy Exposure	5.5-9
5.5-11	1991 to 2001 Timber Harvest Plans	5.5-9
5.5-12	Instream Sediment and Temperature Sampling Sites, Wheatfield Fork Subbasin.....	5.5-18
5.5-13	Maximum Weekly Average Temperature (MWAT) Ranges For The Wheatfield Fork Subbasin From 1995-2001 (Data From GRI And GRWC Continuous Monitoring Devices).....	5.5-19
5.5-14	MWAT Temperature Ranges in the Wheatfield Fork Subbasin for the Period of Record, 1995-2001 Overlaid on the Lansat Vegetation Layer for 2000	5.5-20
5.5-15	Canopy Cover and Canopy Vegetation Types by Percent Survey Length in Nine Tributaries, Wheatfield Fork Subbasin 1995 and 2001, Gualala River Watershed, California	5.5-24
5.5-16	Percent of Cobble Embeddedness in all Pool Tails in the Wheatfield Fork Subbasin 1995 and 2001, Gualala River Watershed, California.....	5.5-24
5.5-17	Pools by Maximum Depth and Percent Survey Length in the Wheatfield Fork Subbasin 1995 and 2001, Gualala River Watershed, California.....	5.5-25

5.5-18 Average Pool Shelter Ratings in the Wheatfield Fork Subbasin 1995 and 2001, Gualala River Watershed, California 5.5-25

5.5-19 Type of Pool Cover by Percent of Pool Survey Length in the Wheatfield Fork Subbasin 1995 and 2001, Gualala River Watershed, California..... 5.5-26

5.5-20a Potential Restoration Sites and Habitat Limiting Factors for the Wheatfield Fork Subbasin, Gualala River Watershed..... 5.5-32

5.5-20b Explanation for Potential Restoration Sites and Habitat Limiting Factors for the Gualala River Watershed Map..... 5.5-33

5.6-1 Gualala Mainstem/South Fork Subbasin 5.6-2

5.6-2 Historic Events and Data Used in the NCWAP Assessment for the Main Gualala/South Fork Subbasin 5.6-3

5.6-3 Geologic and Geomorphic Features Related to Landsliding - Gualala Mainstem/South Fork Subbasin, Northern Portion 5.6-4

5.6-4 Relative Landslide Potential with Geologic and Geomorphic Features – Gualala Mainstem/South Fork Subbasin, Northern Portion 5.6-5

5.6-5 Geologic and Geomorphic Features Related to Landsliding - Gualala Mainstem/South Fork Subbasin, Southern Portion 5.6-6

5.6-6 Relative Landslide Potential with Geologic and Geomorphic Features Gualala Mainstem/South Fork Subbasin, Southern Portion 5.6-7

5.6-7 1942 Bank-to-Bank Exposure and Partial to Entire Cover Over Blue Line Streams 5.6-8

5.6-8 Overstory Shade Canopy Elimination, Upper South Fork, June 1965 5.6-9

5.6-9 Conversion Project Removing Conifers Over the Creek in an Upper McKenzie Creek Tributary, Leaving Hardwoods Upslope 5.6-9

5.6-10 Mid-Century Stand Replacement Operations, Streamside Roads and Landings 5.6-10

5.6-11 1968 Bank-to-Bank Stream Exposure and 1999 Bank-to-Bank Stream Exposure 5.6-11

5.6-12 1991 to 2001 Timber Harvest Plans 5.6-12

5.6-13 Instream Sediment and Temperature Sampling Sites, Gualala Main/South Fork Subbasin 5.6-15

5.6-14 Maximum Weekly Average Temperatures for the Main/South Fork Subbasin, 1994-2001, From Continuous Temperature Monitors Maintained by GRI and GRWC 5.6-16

5.6-15 MWAT Temperature Ranges in the Gualala Main/South Fork Subbasin for the Period of Record, 1994-2001 Overlaid on the LandSat Vegetation Layer for 2000..... 5.6-17

5.6-16 Canopy Cover and Canopy Vegetation Types in the Seven Tributaries Surveyed, South Fork Subbasin 1999 and 2001, Gualala River Watershed, California..... 5.6-20

5.6-17 Cobble Embeddedness in the South Fork Subbasin 1999 2001, Gualala River Watershed, California..... 5.6-21

5.6-18 Pools by Maximum Depth and Percent Survey Length in the South Fork Subbasin 1999 and 2001, Gualala River Watershed, California 5.6-21

5.6-19 Average Pool Shelter Ratings in the South Fork Subbasin 1999 and 2001, Gualala River Watershed, California 5.6-22

5.6-20 Types of Pool Cover by Percent of Pool Survey Length in the South Fork Subbasin 1999 and 2001, Gualala River Watershed, California 5.6-22

5.6-21a Potential Restoration Sites and Habitat Limiting Factors for the Gualala Mainstem/South Fork Subbasin, Gualala River Watershed, Northern and Southern Portions 5.6-27

5.6-21b Explanation for Potential Restoration Sites and Habitat Limiting Factors for the Gualala River Watershed Map 5.6-28

LIST OF TABLES

ES-1	Summary of Gualala River Watershed Conditions and Recommended Actions by Subbasins Based Largely on Habitat Inventory Surveys.....	ES-26
2-1	Database Dictionary for GIS Mapped Fluvial Geomorphic Attributes	2-10
2-2	In-Channel Criteria Used in the Assessment of Water Quality Data	2-13
3-1	Characteristics and Land Ownership of the Five Gualala River Subbasins for the NCWAP Assessment.....	3-3
3-2	Estimated Water Uses in the Gualala River Watershed	3-5
3-3	Gualala River Watershed - Stream Characteristics Representing Sediment Sources or Storage.....	3-8
3-4	Timber Harvest History - Gualala Watershed.....	3-13
3-5	Summary of Historic (1964-1981) Stream Surveys Conducted in the Gualala River Watershed, California.....	3-23
3-6	Habitat Inventory Target Values Taken from the California Salmonid Stream Habitat Restoration Manual (Flosi et al 1998).....	3-27
3-7	Summary of Current (1995, 1997, and 2001) Conditions Based Upon Habitat Inventory Surveys from the Gualala River Watershed, California	3-29
3-8	Comparison Between Historic Habitat Conditions Observed in 1964 with Current Habitat Inventory Surveys Based Upon Quantitative Measurements in 1995, 1999 and 2001 from the Gualala River Watershed, CA.....	3-31
3-9	Current Fish Species in the Gualala River Watershed, California	3-33
3-10	Coho Salmon and Steelhead Trout Data Summary by Decade, Gualala River Watershed, California.....	3-35
3-11	Historic Coho Distribution (Brown and Moyle 1991).....	3-39
3-12	Current 2001-2002 coho salmon distribution in the Gualala River Watershed, California (Gualala Redwoods, Inc. and CDFG unpub data 2002).....	3-40
3-13	Historic Steelhead Trout (<i>Oncorhynchus mykiss</i>) Distribution Based Upon CDFG Stream Surveys from 1960s and 1970s in the Gualala River Watershed, California.....	3-41
3-14	Non-salmonid aquatic species documented in the Gualala River Watershed, California.	3-44
4.1-1	Reference Curve Metrics for the EMDS Stream Reach Condition Model	4-12
4.1-2	Reference Curve Metrics for the EMDS for the Sediment Production Risk Model	4-13
4.2-1	Acres and Percent Area of Historically Active Landslides Associated with Land Use or Type for the Gualala River Watershed.....	4-19
4.2-2	Acres and Percent of Area by Relative Landslide Potential and Land Use or Type, Gualala River Watershed.....	4-21
4.2-3	Comparison of Historic Instream Roads with Modern Roads within 50 Feet of Blue Line Streams	4-25

4.2-4	THP Yarding Methods By Subbasin, 1991-2001, Gualala River Watershed	4-28
4.2-5	Length, Number and Percent of Gullies in 1999/2000 Aerial Photographs by Watershed and Subbasin, Gualala River Watershed.	4-32
4.2-6	GIS Mapped Fluvial Geomorphic Attributes Considered Detrimental to Optimum Habitat for Anadromous Salmonids	4-33
4.2-7	Mapped Changes Between 1984 and 1999/ 2000 in Fluvial Geomorphic Channel Disturbances Detrimental to Habitat for Anadromous Salmonids in the Five Subbasins.	4-34
4.3-1	Limiting Factors Affecting Salmonid Health and Production Based Upon Habitat Inventory Surveys Conducted in 1999 and 2001, and EMDS Scores in the Gualala River Watershed, California	4-38
4.4-1	Summary of Habitat Inventory Survey Data From 1995, 1999, and 2001 for the Gualala River Tributaries, Gualala River Watershed, CA	4-43
4.4-2	Priorities for Restoration for the Gualala River Tributaries, Gualala River Watershed.....	4-45
4.4-3	Gualala River Watershed General Hydrologic Characteristics (Table 1 of Appendix 2).....	4-48
4.5-1	Potential Salmonid Refugia Based Upon Habitat Inventory Survey, EMDS Stream Reach, Professional Judgment, and Local Expertise in the Gualala River Watershed, California	4-52
5.1-1	Riparian Vegetation Inventory of the Gualala River Estuary/Coastal Lagoon, February 2002.....	5.1-3
5.2-1	North Fork Subbasin Stand Replacement Operations 1932 - 1973 - Total Area = 30,636 acres.....	5.2-7
5.2-2	North Fork Subbasin Timber Harvest Operations 1974 – 2001 - Total Area = 30,636 Acres	5.2-10
5.2-3	North Fork Subbasin Stream Characteristics Representing Sediment Sources or Storage.	5.2-13
5.2-4	EMDS Ratings for Maximum Weekly Average Temperatures (MWATs) in the North Fork Subbasin	5.2-14
5.2-5	Summary of Historic (1964) Stream Surveys Conducted in the North Fork Subbasin, Gualala River Watershed, California	5.2-19
5.2-6	Habitat Inventory Target Values taken from the <i>California Salmonid Stream Habitat Restoration Manual</i> (Flosi et al 1998).....	5.2-19
5.2-7	Summary of Current (1995, 1997, and 2001) Conditions Based Upon Habitat Inventory Surveys from the North Fork Subbasin, Gualala River Watershed, California	5.2-20
5.2-8	Summary of Watershed Cooperative Monitoring Program large woody debris data, North Fork Subbasin (1998 - 2000)	5.2-24
5.2-9	Comparison Between Historic Habitat Conditions Observed in 1964 with Current Habitat Inventory Surveys Based Upon Quantitative Measurements in 2001 from the North Fork Subbasin, Gualala River Watershed, California	5.2-25

5.2-10 Ecological Management Decision Support (EMDS) Reach Model Scores on Salmonid Health and Productivity Suitability for the North Fork Subbasin, Gualala River Watershed, California , Based Upon Habitat Inventory Surveys Conducted in 2001 5.2-26

5.2-11 Limiting Factors in the North Fork Subbasin Affecting Salmonid Health and Production Based Upon Habitat Inventory Surveys Conducted in 2001 and EMDS Scores in the North Fork Subbasin, California 5.2-27

5.2-12 Priorities for Restoration for the North Fork Subbasin 5.2-28

5.2-13 Refugia Categories for Surveyed Tributaries in the North Fork Subbasin, Gualala River Watershed, California..... 5.2-29

5.3-1 Rockpile Subbasin Stand Replacement Operations 1942 – 1973 - Total Area = 22,390 acres..... 5.3-8

5.3-2 Rockpile Subbasin Timber Harvest Operations – 1974 – 2001 - Total Area = 22,390 acres..... 5.3-9

5.3-3 Rockpile Subbasin Stream Characteristics Representing Sediment Sources or Storage 5.3-12

5.3-4 EMDS Ratings for Maximum Weekly Average Temperatures (MWATs) in the Rockpile Subbasin..... 5.3-12

5.3-5 Habitat Inventory Target Values Taken From the *California Salmonid Stream Habitat Restoration Manual* (Flosi et al 1998)..... 5.3-16

5.3-6 Summary of Current (2001) Conditions Based Upon Habitat Inventory Surveys from the Rockpile Subbasin, Gualala River Watershed, California 5.3-16

5.3-7 Watershed Cooperative Monitoring Program Large Woody Debris Survey, Rockpile Subbasin (1998-2001) 5.3-19

5.3-8 Ecological Management Decision Support (EMDS) Reach Model Scores on salmonid health and productivity suitability for the Rockpile Subbasin, CA., based upon habitat inventory surveys conducted in 1999 and 2001 5.3-20

5.3-9 Limiting Factors for the Rockpile Subbasin Affecting Salmonid Health and Production Based Upon Habitat Inventory Surveys Conducted in 1999 and 2001 and EMDS scores in the Gualala River Watershed, California..... 5.3-21

5.3-10 Priorities for Restoration for the Rockpile Subbasin from the 2001 Habitat Inventory Data 5.3-21

5.4-1 Buckeye Subbasin Stand Replacement Operations 1942 – 1973 - Total Area = 25,768 acres..... 5.4-8

5.4-2 Buckeye Subbasin timber harvest operations – 1974 – 2001 - Total Area = 25,768 acres .. 5.4-9

5.4-3 Buckeye Subbasin Stream Characteristics Representing Sediment Sources or Storage 5.4-14

5.4-4 EMDS Ratings for Maximum Weekly Average Temperatures (MWATs) in the Buckeye Subbasin 5.4-18

5.4-5 Summary of Historic (1964-1982) Conditions Based Upon Stream Surveys Conducted in the Buckeye Subbasin Gualala River Watershed, California..... 5.4-18

5.4-6	Habitat Inventory Target Values Taken from the <i>California Salmonid Stream Habitat Restoration Manual</i> (Flosi et al 1998).....	5.4-19
5.4-7	Summary of Current (2001) Conditions Based Upon Habitat Inventory Surveys from the Buckeye Subbasin, Gualala River Watershed, California.....	5.4-19
5.4-8	Summary of Watershed Cooperative Monitoring Program Large Woody Debris Data, Buckeye Subbasin, (1998 - 2000).....	5.4-22
5.4-9	Comparison Between Historic Habitat Conditions Observed in 1964 with Current Habitat Inventory Surveys Based Upon Quantitative Measurements in 2001 from the Buckeye Subbasin Gualala River Watershed, California.....	5.4-22
5.4-10	Ecological Management Decision Support (EMDS) Reach Model Scores on Salmonid Health and Productivity Suitability for the Buckeye Subbasin Gualala, California, Based Upon Habitat Inventory Surveys Conducted in 2001.....	5.4-23
5.4-11	Limiting Factors for the Buckeye Subbasin Affecting Salmonid Health and Production Based Upon Habitat Inventory Surveys Conducted in 2001 and EMDS Scores in the Gualala River Watershed, California.....	5.4-23
5.4-12	Priorities for Restoration in the Buckeye Subbasin Based Upon 2001 Surveys.....	5.4-24
5.5-1	Wheatfield Fork Subbasin Timber Harvest Operations 1932 – 1973 - Total Area = 74,444 acres.....	5.5-8
5.5-2	Wheatfield Fork Subbasin Timber Harvest Operations 1974 – 2001 -Total Area = 74,444 acres.....	5.5-11
5.5-3	Wheatfield Fork Subbasin Stream Characteristics Representing Sediment Sources or Storage.....	5.5-16
5.5-4	EMDS Ratings for Maximum Weekly Average Temperatures (MWATs) in the Wheatfield Fork Subbasin.....	5.5-17
5.5-5	Summary of Historic (1964-1970) Stream Surveys Conducted in the Wheatfield Fork Subbasin Gualala River Watershed, California.....	5.5-21
5.5-6	Habitat Inventory Target Values Taken from the <i>California Salmonid Stream Habitat Restoration Manual</i> (Flosi et al 1998).....	5.5-22
5.5-7	Summary of Current (1995 and 2001) Conditions Based Upon Habitat Inventory Surveys from the Wheatfield Fork Subbasin, Gualala River Watershed, California.....	5.5-23
5.5-8	Summary of the Watershed Cooperative Monitoring Program Large Woody Debris Survey, Wheatfield Fork Subbasin (1998 - 2001).....	5.5-26
5.5-9	Comparison Between Historic Habitat Conditions Observed in 1964, 1965, and 1970 with Current Habitat Inventory Surveys Based Upon Quantitative Measurements in 1995 and 2001 from the Wheatfield Fork Subbasin, Gualala River Watershed, California.....	5.5-27
5.5.10	Ecological Management Decision Support (EMDS) Reach Model Scores on Salmonid Health and Productivity Suitability for the Wheatfield Fork Subbasin, Based Upon Habitat Inventory Surveys Conducted in 1995 and 2001.....	5.5-28

5.5-11 Limiting Factors for the Wheatfield Fork Subbasin Affecting Salmonid Health and Production Based Upon Habitat Inventory Surveys Conducted in 2001 and EMDS Scores in the Gualala River Watershed, California..... 5.5-29

5.5-12 Limiting Factors Affecting Salmonid Health and Production in the Fuller Creek Watershed Located in the Wheatfield Fork Subbasin of the Gualala River Watershed, California Based Upon Habitat Inventory Surveys Conducted in 1995 5.5-29

5.5-13 Priorities for Restoration in the Wheatfield Fork Subbasin Based Upon 1995 and 2001 Data 5.5-30

5.6-1 Gualala Mainstem/South Fork Subbasin Stand Replacement Operations 1932 – 1973 - Total Area = 40, 756 acres..... 5.6-10

5.6-2 Gualala Mainstem/South Fork Subbasin Timber Harvest Operations – 1974 – 2001 - Total Area = 40, 756 acres..... 5.6-12

5.6-3 Gualala Mainstem/South Fork Subbasin Subbasin Stream Characteristics Representing Sediment Sources or Storage 5.6-13

5.6-4 Ecological Management Decision Support (EMDS) Ratings for Maximum Weekly Average Temperatures (MWATS) in the Gualala Main/South Fork Subbasin 5.6-14

5.6-5 Summary of Historic (1964-1981) Stream Surveys Conducted in the South Fork Subbasin 5.6-18

5.6-6 Habitat Inventory Target Values Taken from the *California Salmonid Stream Habitat Restoration Manual* (Flosi et al 1998)..... 5.6-19

5.6-7 Summary of Current (1999 and 2001) Conditions Based Upon Habitat Inventory Surveys From the Gualala Mainstem/South Fork Subbasin, Gualala River Watershed, California 5.6-20

5.6-8 Summary of Watershed Cooperative Monitoring Program Large Woody Debris Surveys, Gualala Mainstem and Lower South Fork Subbasin (1998 - 2001)..... 5.6-23

5.6-9 Comparison Between Historic Habitat Conditions Observed in 1964 with Current Habitat Inventory Surveys Based Upon Quantitative Measurements in 2001 from the Gualala Mainstem/South Fork Subbasin, Gualala River Watershed, California 5.6-23

5.6-10 Ecological Management Decision Support (EMDS) Reach Model Scores on Salmonid Health and Productivity Suitability for the South Fork Subbasin, California, Based Upon Habitat Inventory Surveys Conducted in 1999 and 2001..... 5.6-24

5.6-11 Limiting Factors for the South Fork Mainstem Subbasin Affecting Salmonid Health and Production Based Upon Habitat Inventory Surveys Conducted in 1999 and 2001 and EMDS Scores in the Gualala Basin, California..... 5.6-25

5.6-12 Priorities for Restoration for the Mainstem/South Fork Subbasin Based Upon 1999 and 2001 Data..... 5.6-25

LIST OF PLATES -- ON CD

Plate 1, Sheet 1	Geologic and Geomorphic Features Related to Landsliding, Gualala River Watershed, Sonoma and Mendocino Counties, California Sheet 1 of 3, Northern Portion
Plate 1, Sheet 2	Geologic and Geomorphic Features Related to Landsliding, Gualala River Watershed, Sonoma and Mendocino Counties, California, Sheet 2 of 3, Central Portion Geologic and Geomorphic Features Related to Landsliding, Gualala River Watershed, Sonoma and Mendocino Counties, California, Sheet 3 of 3, Southern Portion
Plate 2, Sheet 1	Relative Landslide Potential with Geologic and Geomorphic Features, Gualala River Watershed, Sonoma and Mendocino Counties, California, Sheet 1 of 3, Northern Portion
Plate 2, Sheet 2	Relative Landslide Potential with Geologic and Geomorphic Features, Gualala River Watershed, Sonoma and Mendocino Counties, California, Sheet 2 of 3, Central Portion
Plate 2, Sheet 3	Relative Landslide Potential with Geologic and Geomorphic Features, Gualala River Watershed, Sonoma and Mendocino Counties, California, Sheet 3 of 3, Southern Portion
Plate 3	Potential Restoration Sites and Habitat Limiting Factors for the Gualala River Watershed